



Items highlighted are not all of the hazards or pot holes, but the worst. Ride with head up and take care!



Photos on the next pages

**Items highlighted are not all of the hazards or pot holes, but the worst.
Ride with head up and take care!**

Number	Description	Photo
1	sunken road surface	 A photograph of a two-lane asphalt road stretching into the distance. The road surface appears uneven and sunken in the center. On the left side of the road, there is a dense line of green bushes and tall grass. On the right side, there is a well-manicured green hedge. A white dashed line runs down the center of the road, and a white arrow points forward on the right lane. The sky is blue with some light clouds. The shadow of the person taking the photo is visible in the bottom left corner of the image.


Items highlighted are not all of the hazards or pot holes, but the worst.

Ride with head up and take care!

Number	Description	Photo
2	pothole	 A photograph of a two-lane asphalt road with white dashed lane markings. On the left side of the road, there is a metal storm drain grate. Further down the road, there is a large, irregular pothole where the asphalt surface has broken up and is missing. The road is bordered by green grass and vegetation on both sides.


Items highlighted are not all of the hazards or pot holes, but the worst.

Ride with head up and take care!

Number	Description	Photo
3	Large pothole	

Items highlighted are not all of the hazards or pot holes, but the worst.

Ride with head up and take care!

Number	Description	Photo
4	Large pothole	

Items highlighted are not all of the hazards or pot holes, but the worst.

Ride with head up and take care!


Number	Description	Photo
5	Sunken drain cover at top of hill.	

**Items highlighted are not all of the hazards or pot holes, but the worst.
Ride with head up and take care!**

Number	Description	Photo
6	Sunken drain cover	 A photograph showing a rectangular, textured metal drain cover that is sunken into the asphalt road surface. The cover is located on the left side of the road, adjacent to a grassy shoulder. A white painted line runs along the edge of the road, and the shadow of the person taking the photo is visible on the asphalt in the foreground.


Items highlighted are not all of the hazards or pot holes, but the worst.

Ride with head up and take care!

Number	Description	Photo
7	Sunken drain cover	


Items highlighted are not all of the hazards or pot holes, but the worst.

Ride with head up and take care!

Number	Description	Photo
8	Pothole on left hand bend	 A photograph taken from a first-person perspective, likely from a bicycle, showing a road ahead. The road is paved with asphalt and has a white dashed line on the left side. To the left of the road is a grassy area with some weeds. A pothole is visible in the road, located near the white line. The road curves to the left. The bottom of the frame shows the front wheel of a bicycle.

Items highlighted are not all of the hazards or pot holes, but the worst.

Ride with head up and take care!

Number	Description	Photo
9	Sunken road surface	

**Items highlighted are not all of the hazards or pot holes, but the worst.
Ride with head up and take care!**

Number	Description	Photo
10	Missing drain cover	